

User.

Monday, 18/08/2008 10:26:53 AM

Julie Lecoca

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

: ARM

: N/A

: D

: D3560042

: 10/09/2008

: D3560 REV D

Customer : CU-DAR001 Dart Helicopters Services

.lob Number : 41287

Estimate Number : 12882

P.O. Number

This Issue : 18/08/2008

: NC

Prsht Rev. First Issue : 11

: 35404 Previous Run

Written By

Checked & Approved By

Comment

est rev B Est Rev:C

: Est Rev:A

S.O. No. :

Type

ECN 987 07.10.09

ECN1048 07-12-18

EC

: MACHINED PARTS

EC verified by: DD DD verified by: EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

2.0

M6061T6B0500X05000

6061-T6 Bar .500 x 5.00



Comment: Qty.: 1.4648 f(s)/Unit Total: 14.6475 f(s)

6061-T6 Bar 0.50" x 5.00"

Batch: M 10907 5

BAND SAW BAND SAW



Comment: BAND SAW

Cut blanks 16.750" long

3.0 HAAS1 HAAS CNC VERTICAL MACHINING #1



Comment: HAAS CNC VERTICAL MACHINING #1


1- Mill as per Folio FA694 Rev: 44 & Dwg D3560 Rev:

2-C'sink 0.196" hole on manual mill as per dwg D3560

3-Deburr per dwg D3560

4.0 QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE



Each













Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto					
					5	- 1						
Part No		PAR #: Fault Category: N		No DQA		7-						

NCF	₹:	WORK ORDER NON-CONFORMANCE (NCR)							
	1	3 1	STED Description of NC Corrective Action Section B				Verification	Ammununt	Annewate
DA	TE	STEP	Section A	Initial Chief Eng		ign & Date	Section C	Approval Chief Eng	Approval QC Inspector
									-10
									4
	-			7-37					15
8						70			1
								·	
	- 4		· · · · · · · · · · · · · · · · · · ·						The State
									4.5
								L	

NOTE: Date & initial all entries

Monday, 18/08/2008 10:26:53 AM User: ' Julie Lecocq **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 41287 Part Number: D3560042 Job Number: Seq. #: Description: Machine Or Operation: SECOND CHECK Comment: SECOND CHECK D35921 Comment: Qty.: 10.0000 Each(s) 1.0000 Each(s)/Unit Total 7.0 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (65 deg C) 8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) QC5 INSPECT WORK TO CURRENT STE Comment: INSPECT WORK TO CURRENT STEP VISUAL WELDING INSPECTION 9.0 Comment: VISUAL WELDING INSPECTION 08-09-09

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES	WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
	The state of the state of								

Part No: D3560-012 PAR #: NA Fault Category: Rod Ras. Large NCR: Yes No DQA: Date: O8189/22

QA: N/C Closed: D Date: O8189/22

WORK ORDER NON-CONFORMANCE (NCR) NCR: 41285 **Corrective Action** Section B Description of NC Verification Approval QC Inspector Approval DATE STEP Sign & **Action Description** Initial Section A Chief Eng Section C Chief Eng Date Chief Eng one Arm was found with 08/09/17 no Replace By & a chack in the phote 035924 SAD 81919 from welpay R.C. grain runs wlong the AS DES EMOU'T From DAVID Stephons weld. to Alon stocker on 81910 @ 1:36 pm See (AR08-026

NOTE: Date & initial all entries


Monday, 18/08/2008 10:26:53 AM Date: User: ' Julie Lecocq **Process Sheet** Customer: CU DAR001 Dart Helicopters Services Drawing Name: ARM Part Number: D3560042 Job Number: 41287 Job Number: Seq. #: Machine Or Operation: Description: HAND FINISHING RESOURCE #1 HAND FINISHING1 10.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 11.0 QC3 INSPECT POWDER COAT Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 1.0000 Each(s)/Unit Jotal: 10.0000 Each(s) Comment: Qty.: Spacer SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 13.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Press bushing in D3560 arm per dwg D3562 INSPECT WORK TO CURRENT STEP 14.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING ' PACKAGING RESOURCE #1 15.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: QC21 16.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Form: rprocess


Page 3


Dart Agrospace I to


Part Action page 21									
W/O:			V	ORK ORDER CHANGE	ES				
DATE	STEP	PROC	EDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			ē						
Part No		PAR #:	_ Fault Cat	tegory:					
							i:	_ Date: _	rd
NCR:		W	ORK ORI	DER NON-CONFORMA	NCE (NC	R)			3
DATE	CTED	Description of NC		Corrective Action Section	n B	Verification Approval			Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Secti		Chief Eng	QC Inspector
NOTE									
NOTE: Da	are & initia	al all entries							





















DART AEROSPACE LTD	Work Order:	41287
Description: Arm	Part Number:	D3560-2
Inspection Dwg: D3560 Rev: B		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Pro	totype
---------------------	--------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	-506	/			
Ø0.196	+0.005/-0.001	-196				
Ø1.000	+0.010/-0.001	1.004				
0.500	+/-0.010	-491	1			
0.250	+/-0.010	250	/			
0.275	+/-0.010	-274				
0.188	+/-0.010	-189	/			
2.000	+/-0.010	2.000	/			
1.700	+/-0.010	1.700	/			
Ø0.385 x 100°	+/-0.010 × 0.5°	395X100°	/			
0.250 Deep	+/-0.010	246	/			

Measured by:	ユエ	Audited by:	Prototype Approval:	N/A
Date:	08/08/25	Date: 08/09/02	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.01.17	New Issue	KJ/JLM 1.A	
В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM	臣



From: David Shepherd [mailto:dshepherd@dartaero.com]

Sent: September 10, 2008 1:36 PM

To: 'Alan Stocker'

Cc: 'Chris Provencal'; 'Mike Petsche'; 'Bill Beckett'; 'Susanne Sheldon'

Subject: RE: D3560-044 & -042 Cracking

Alan.

Thanks for the pictures.

I am not comfortable with any sort of repair to these parts.

I think that all 14 parts should be scrapped.

And, at the risk of stating the obvious, we need to revisit the manufacturing process of this joint.

My preference, as it was a couple of years ago, is to eliminate this weld.

However, the geometry in that area is a little tricky. Suggest we generate an NCR or PAR or whatever.

David

From: Alan Stocker [mailto:astocker@dartaero.com] Sent: Wednesday, September 10, 2008 10:26 AM

To: 'David Shepherd'

Cc: 'Chris Provencal'; 'Mike Petsche' Subject: D3560-044 & -042 Cracking

Good morning,

We have 13x D3560-044 and 1x D3560-042 that have cracks all but 1 in the same location. Attached image D3560-044 Crack 1 shows where 13 of the 14 cracks occurred. D3560-044 Crack 2 shows where the other crack occurred. The cracks shown in D3560-044 Crack 1 vary in depth from roughly 3/32 to ½ inch. I discussed this with Chris and Peter the consensus opinion is the parts are scarp. Further discussion with Chris indicates that changing grain direction to 45 degree on the sheet metal part may lower the scrap rate but not eliminate it. This has been done on a previous deviation with a less scrap. D3560-044 Crack 2 appears to just be an anomaly.

Please disposition all 14 parts.

Regards,

Alan Stocker Mechanical Designer

Dart Aerospace Ltd. 1270 Aberdeen Street Hawkesbury, Ontario CANADA K6A 1K7

Phone: 613 632 5200 x 241 FAX: 1 613 632 5246

astocker@dartaero.com

